

**BEAGLE B.121 PUP SERIES SERVICE BULLETIN (SB) INDEX**

<b>SB No.</b>	<b>Series</b>	<b>Issue/Revision</b>	<b>Dated</b>	<b>Description/Title</b>	<b>Compliance/Comments</b>
B121/00	ALL	Rev 11	01/09/2010	BEAGLE PUP - INDEX OF SERVICE BULLETINS AND SERVICE LETTERS	INFORMATION
B121/001	See SB		01/10/1968	ELEVATOR TRIM POSITION INDICATOR - LOSS OF ENGAGEMENT	SUPERSEDED BY MOD BE16
B121/002	ALL	Iss 2	14/11/1969	UNDERCARRIAGE WHEEL HUB NUTS - TIGHTNESS CHECK	SUPERSEDED BY BULLETINS B121/6 & B121/19
B121/003	1 & 2		20/01/1969	AIRFRAME LUBRICATION SPECIFICATIONS	SUPERSEDED BY AL 7 TO MAINTENANCE SCHEDULE
B121/004	1		19/02/1969	OPERATION IN LOW TEMPERATURES - INTRODUCTION OF OIL COOLER BLANK	SUPERSEDED BY MOD BE210
B121/005	See SB		04/06/1969	WING FUEL TANKS - CRACKS IN LOWER FORWARD EDGE	OUT-OF-DATE COMPLIANCE REQUIRED BY 1/9/69 MOD BE264 REFERS
B121/006	ALL		28/05/1969	MAIN WHEEL HUBS PT. NO. AH52595 - INTRODUCTION OF MODIFICATION BE280	OUT-OF-DATE COMPLIANCE REQUIRED BY 1/7/69 MOD BE280 REFERS
B121/007	ALL		16/06/1969	FIRE EXTINGUISHER - INTRODUCTION OF WIRE LOCKING TO RETAIN CLIP	SUPERSEDED BY MOD BE312
B121/008	See SB		09/07/1969	RUDDER CONTROL TORQUE TUBE LEVER - LOOSENESS OF ATTACHMENT RIVETS	PASSED COMPLIANCE DATE. MOD BE318 REFERS
B121/009	ALL		18/07/1969	INTRODUCTION OF 'NO SMOKING' PLACARD	MANDATORY SUPERSEDED BY MOD BE344
B121/010					SUPERSEDED BY BULLETIN B121/11
B121/011	See SB		22/10/1969	INTRODUCTION OF REPLACEMENT ENGINE BEARERS - MOD BE.349	MANDATORY SUPERSEDED BY MOD BE349

SB No.	Series	Issue/Revision	Dated	Description/Title	Compliance/Comments
B121/012	ALL		14/11/1969	MAIN UNDERCARRIAGE SHOCK ABSORBER UNITS - SEAL FAILURES	RECOMMENDED
B121/013	2 & 3		14/11/1969	NOSE SHOCK ABSORBER AND NOSE WHEEL TYRE - INFLATION PRESSURES	SUPERSEDED BY MOD BE391 AND BE392
B121/014					SUPERSEDED BY BULLETIN B121/69
B121/015	ALL		14/11/1969	PICKETTING - CORRECT PROCEDURE	RECOMMENDED
B121/016					SUPERSEDED BY BULLETIN B121/22
B121/017	ALL		28/11/1969	CABIN FIRE EXTINGUISHER - MANDATORY REQUIREMENT	MANDATORY SUPERSEDED BY MOD BE251 OR BE347
B121/018	See SB		28/11/1969	BAGGAGE LASHING RINGS - CAA REQUIREMENTS	SUPERSEDED BY MOD BE78 OR BE381
B121/019	ALL		28/11/1969	NOSE WHEEL ASSEMBLIES PT. NO. AH52594. INTRODUCTION OF MODIFICATION BE382	OUT-OF-DATE COMPLIANCE REQUIRED BY 31/12/69. MOD BE382 REFERS
B121/020					OUT-OF-DATE AVCO LYCOMING BULLETIN NO LONGER ACTIVE
B121/021	ALL		19/01/1970	FUEL TANKS - NON RETURN VALVES - DELETION OF SPRING	MANDATORY
B121/022	ALL		19/05/1970	FUEL TANKS - DEFINITION OF STANDARD	SUPERSEDED BY MODS BE364 OR BE404 WITH BE207 OR BE404 WITH BE249
B121/023	ALL		24/06/1970	INTERNAL DOOR LOCK OPERATING HANDLE - FAILURE TO FULLY ENGAGE	RECOMMENDED
B121/024	2		24/06/1970	OIL COOLER - CRACKING OF SUPPORT BAFFLE AND ATTACHMENT FLANGE	RECOMMENDED

SB No.	Series	Issue/Revision	Dated	Description/Title	Compliance/Comments
B121/025					SUPERSEDED BY BULLETIN B121/71
B121/026	2 & 3		23/11/1970	LYCOMING ENGINE INSTALLATION: VACUUM PUMP GASKET - INCORRECT MANUFACTURE	RECOMMENDED
B121/027					SUPERSEDED BY BULLETIN B121/71
B121/028	ALL	Rev 2	10/12/1996	FLYING CONTROLS - CORROSION OF ELEVATOR TORQUE TUBES	MANDATORY.
B121/029					SUPERSEDED BY BULLETIN B121/65
B121/030	ALL		15/06/1971	ENGINE BEARER - CHAFING	MANDATORY
B121/031	ALL	Iss 2	26/03/1973	FUSELAGE LOWER FRAME ASSEMBLY (STN. 82) - DISTORTION AND CRACKING	INFORMATION
B121/032	ALL		21/04/1972	ENGINE CONTROLS INSTALLATION - FAILURE OF KEY WASHER IN FRICTION ASSEMBLY	INFORMATION
B121/033	ALL	Iss 2	18/12/1972	FLAP ACTUATOR JACK SCREW - LUBRICATION	RECOMMENDED
B121/034					SUPERSEDED BY BULLETIN B121/66
B121/035					OUT-OF-DATE R.R. BULLETIN NO LONGER ACTIVE
B121/036					OUT-OF-DATE R.R. BULLETIN NO LONGER ACTIVE
B121/037					CANCELLED 31/08/05
B121/038					CANCELLED 31/08/05

SB No.	Series	Issue/Revision	Dated	Description/Title	Compliance/Comments
B121/039					SUPERSEDED BY BULLETIN B121/75
B121/040					CANCELLED 31/08/05
B121/041					CANCELLED 31/08/05
B121/042					CANCELLED 31/08/05
B121/043					SUPERSEDED BY BULLETIN B121/45
B121/044					CANCELLED 31/08/05
B121/045					CANCELLED 31/08/05
B121/046					CANCELLED 31/08/05
B121/047					CANCELLED 31/08/05
B121/048					OUT-OF-DATE R.R. BULLETIN NO LONGER ACTIVE
B121/049	1		15/10/1973	NOTIFICATION OF ROLLS ROYCE SERVICE BULLETIN NO. T244/1 - TELEDYNE CONTINENTAL ENGINE - VALVE GUIDE INSPECTION	MANDATORY
B121/050					CANCELLED 31/08/05
B121/051	2 & 3	Iss 2	30/01/1975	NOTIFICATION OF BENDIX SERVICE BULLETIN NO. 556B - REPLACEMENT OF MAGNETO DRIVE SHAFT BUSHING	MANDATORY. OUT-OF-DATE. COMPLIANCE REQUIRED BY 24/3/75

SB No.	Series	Issue/Revision	Dated	Description/Title	Compliance/Comments
B121/052					CANCELLED 31/08/05
B121/053					OUT-OF-DATE. AVCO LYCOMING SERVICE BULLETIN NO LONGER ACTIVE
B121/054	ALL		30/10/1973	NOTIFICATION OF AUTOMOTIVE PRODUCTS LTD. SERVICE BULLETIN NO. 32-251 REVISION 1 - CRACK TESTING OF SPHERICAL BEARING OF MAIN SHOCK ABSORBER UNIT	INFORMATION
B121/055	ALL		23/01/1974	NOTIFICATION OF DUNLOP AVIATION DIVISION SERVICE BULLETIN NO. 32-658 - MAIN WHEEL DAMAGE IN VICINITY OF BRAKE DRIVE SLOTS	RECOMMENDED
B121/056					CANCELLED 31/08/05
B121/057					SUPERSEDED BY BULLETIN B121/67
B121/058					CANCELLED 31/08/05
B121/059	ALL		19/11/1974	FLEXIBLE HOSE - BULKHEAD TO PRESSURE GAUGE - OIL/FUEL HOSE, PT. NO. BE.80.10031 - SERVICING AND LIFING	RECOMMENDED
B121/060					SUPERSEDED BY THIS BULLETIN B121/00
B121/061	ALL	Iss 3	05/11/1976	INSPECTION OF FLAP ACTUATING LEVER ASSEMBLIES	MANDATORY
B121/062					SUPERSEDED BY BULLETIN B121/76
B121/063				NOT ISSUED	

SB No.	Series	Issue/Revision	Dated	Description/Title	Compliance/Comments
B121/064					CANCELLED 31/08/05
B121/065	ALL	Iss 2	10/08/2005	INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY	MANDATORY. SUPERSEDES BULLETIN NO. B121/29
B121/066					CANCELLED 31/08/05
B121/067	2 & 3		15/03/1976	ENGINE OVERSPEED - PROCEDURES	MANDATORY. SUPERSEDES BULLETIN NO. B121/57
B121/068					CANCELLED 31/08/05
B121/069	ALL		12/08/1976	NOSE WHEEL STEERING HEAD FAILURE, LOSS OF NOSE WHEEL STEERING	MANDATORY. SUPERSEDED BY MOD NO. BE314
B121/070					CANCELLED 31/08/05
B121/071	ALL		29/12/1976	FAILURE OF RUDDER CONTROL LEVER (FUSELAGE STATION 217.75)	MANDATORY. SUPERSEDED BY BULLETIN NO. B121/72
B121/072	ALL		14/06/1977	RUDDER CONTROL LEVER - CLASSIFICATION OF MODIFICATION NO. BE414 AS MANDATORY	MANDATORY. OUT-OF-DATE. COMPLIANCE REQUIRED BY 31/10/77
B121/073	ALL		20/06/1977	RUDDER PEDAL - ANCHORAGES - FAILURE OF RIVETS	MANDATORY. OUT-OF-DATE. COMPLIANCE REQUIRED BY 31/10/77
B121/074	2 & 3	Iss 2	25/10/1977	THROTTLE CABLE ASSEMBLY - INTRODUCTION OF MANDATORY MODS - BE424 AND BE425	MANDATORY
B121/075	1		30/06/1977	FUSELAGE/MAINPLANE ATTACHMENTS. MANDATORY INSPECTIONS	MANDATORY
B121/076	2 & 3		22/06/1978	FUSELAGE/MAINPLANE ATTACHMENTS. MANDATORY INSPECTIONS	MANDATORY

SB No.	Series	Issue/Revision	Dated	Description/Title	Compliance/Comments
B121/077	ALL		25/06/1978	RECOMMENDED PROCEDURES FOLLOWING NOSE WHEEL SHIMMY	
B121/078	1	Rev 1	05/06/1997	CHANGE IN MAGNETO TO ENGINE TIMING AND BAFFLE INSPECTION	NEED FOR COMPLIANCE CANCELLED BY REVISION 1
B121/079	ALL	Rev 1	15/02/1991	CLASSIFICATION OF REPAIR SCHEME NO. BE.03.10169 AS MANDATORY TO MAINPLANES NOT HAVING MOD BE214 EMBODIED	MANDATORY
B121/080	2 & 3		16/11/1978	BENDIX MAGNETOS - INSPECTION OF IMPULSE COUPLINGS AND STOP PINS	MANDATORY
B121/081	1 & 2	Iss 2	03/12/1980	ENGINE MOUNTING STRUCTURE - CRACKING ADJACENT TO UPPER WELD CLUSTERS	MANDATORY
B121/082				NOT ISSUED	
B121/083					CANCELLED 31/08/05
B121/084				NOT ISSUED	
B121/085	See SB		02/12/1980	MAIN WHEEL TYRES - 16" X 6.00" X 5.00"	INFORMATION
B121/086	ALL		29/03/1984	FUSELAGE - CRACKING OF ANGLE, DIAPHRAGM AND FLANGE AT TAILPLANE SPAR ATTACHMENTS	MANDATORY
B121/087					CANCELLED 31/08/05
B121/088					CANCELLED 31/08/05
B121/089				NOT ISSUED	
B121/090				NOT ISSUED	
B121/091	ALL		23/04/1987	FLYING CONTROLS - CONTROL ROD END FITTINGS - SECURITY OF ATTACHMENT	MANDATORY

SB No.	Series	Issue/Revision	Dated	Description/Title	Compliance/Comments
B121/092				NOT ISSUED	
B121/093	1		06/06/1987	PROPELLER - SPINNER REAR BULKHEAD CRACKING	RECOMMENDED
B121/094	ALL		21/06/1988	RUDDER CONTROLS - INCORRECT ASSEMBLY	MANDATORY
B121/095	ALL	Rev 4	08/07/1996	FLYING CONTROLS - FAILURE OF HANDGRIP FITTING ON CONTROL COLUMN	MANDATORY
B121/096	See SB		21/01/1991	REAR CABIN BATTERY COMPARTMENT - INSPECTION FOR ACID SPILLAGE	OPTIONAL
B121/097					CANCELLED 31/08/05
B121/098	ALL		19/12/1992	ENGINE CONTROLS - INSPECTION AND REWORK OF CONTROL CABLES	RECOMMENDED
B121/099	2 & 3	Rev 1	16/11/1993	FUEL SYSTEM - TO PREVENT POSSIBLE DISRUPTION OF FUEL SUPPLY (COVER FOR AERO ACCESSORIES INC. SB NO. 001)	MANDATORY. In accordance with FAA AD 93-11-11.
B121/100	2 & 3		20/01/1995	NDT INSPECTION AT WING ROOT SPAR ATTACHMENT FITTING	MANDATORY.
B121/101	ALL		27/03/1995	NOTIFICATION OF FATIGUE LIFE LIMITATION FOR AIRCRAFT	MANDATORY.
B121/102	ALL	Rev 2	12/01/1998	FUSELAGE - INTRODUCTION OF INSPECTIONS AT THE MAIN-SPAR AND AT THE WING TO FUSELAGE ATTACHMENTS	ORIGINALLY MANDATORY. NOW SUPERSEDED BY SBS B121/105 & B121/106
B121/103	ALL		26/10/1995	LANDING GEAR - BRAKE SYSTEM - TO INSPECT BRAKE TORQUE-TUBE ASSEMBLIES	MANDATORY.
B121/104					CANCELLED 31/08/05

<b>SB No.</b>	<b>Series</b>	<b>Issue/Revision</b>	<b>Dated</b>	<b>Description/Title</b>	<b>Compliance/Comments</b>
B121/105	ALL	Rev 1	22/05/1998	FUSELAGE - TO INTRODUCE INSPECTIONS AT THE MAIN SPAR DOUBLER	MANDATORY, REPLACING (PART OF) SB B121/102
B121/106	ALL		12/01/1998	MAINPLANES - TO INTRODUCE NEW NUTS AT WING TO FUSELAGE MAIN-SPAR ATTACHMENT FITTINGS	MANDATORY, REPLACING (PART OF) SB B121/102
B121/107	ALL	2	31/03/2007	FLEXIBLE HOSES - BULKHEAD TO OIL/FUEL PRESSURE GAUGES - NOTIFICATION OF PUP MODIFICATION NO BE503	INFORMATION. Issue 2 raised to enclose AIL to IPC

**BEAGLE B.121 PUP SERIES SERVICE LETTER (SL) INDEX**

<b>SL no.</b>	<b>Dated</b>	<b>Series affected</b>	<b>Description/title</b>	<b>Compliance/comments</b>
SL B121/0001	29/04/1969	ALL	FUEL LEAKAGE FROM WING TANKS	SUPERSEDED BY BULLETIN B121/5.
SL B121/0002	14/11/1969	ALL	LOCKHEED SHOCK ABSORBER UNITS - AIR CHARGING VALVES LEAKING	INFORMATION
SL B121/0003	14/11/1969	2	LYCOMING 0-320-A2B ENGINES - CARBURETTOR SETTING	INFORMATION
SL B121/0004	18/12/1969	2 & 3	AIRBORNE VACUUM PUMPS - OIL SEAL	INFORMATION
SL B121/0005	09/01/1970	1	ROLLS-ROYCE SERVICE BULLETINS T.151 & T.152	OUT-OF-DATE R.R. BULLETINS NO LONGER ACTIVE
SL B121/0006	20/08/1986	1 & 2	ENGINE MOUNTING BOLTS	INFORMATION
SL B121/0007	20/08/1986	1	SPINNER BULKHEADS CRACKING	INFORMATION
SL B121/0008	24/06/1988	ALL	BRAKE MASTER CYLINDERS	INFORMATION
SL B121/0009	01/09/2006	ALL	NOSE UNDERCARRIAGE SHOCK ABSORBER - ALTERNATIVE SEALS	INFORMATION
SL B121/0010	01/09/2010	ALL	PRODUCT SUPPORT POLICY	INFORMATION – Revised as a result of EASA classification.